

3.3.15 KPI-(252-2002)E4E energy recovery unit and KPI-(502-1002)X4E active unit

Mark	Name
CNn	Connector on PCB
PCNn	Power connector on PCB
DSW3-7	Dip switch for setting
RSW1,2	Rotary switch for for setting
EFR1	Power supply fuse
EF2	PCB fuse
EF3	Fuse for PCN5 connector
EF1-2	Fuse for fans (located in the terminal box)
MS1,2	Motor for automatic swing louver
MV	Micro-computer control expansion valve
FS	Float switch
PCB1,2	Printed circuit board
TB1,2	Terminal board
THM1-5	Thermistor
NF1	Noise filter
TF	Transformer
CN23-30	Aerial connector
RCS	Remote control switch
DMP	Damper
SEGN	7-segments display
PSW1-3	Push button
OA	Outdoor air
RA	Return air

