

# Technical Bulletin

Number	099
Subject	Mitsubishi Service Reference
Date	09 July 2014

We have experienced some issues in the past when quoting Mitsubishi Electric spare parts because some of the production parts may have been changed.

Mitsubishi Electric do not change the model no. of the unit to indicate this **but** they do change the **SERVICE REFERENCE** of the units (please see below).



The model shown is PLA-RP35BA and the service reference is **PLA-RP35BA#2.UK**

*When you make an enquiry for Mitsubishi Electric spare parts please advise (when possible) the **SERVICE REFERENCE** to ensure you get quoted the correct parts at the first time of asking.*